

	Type	Hits	Search Text
1	BRS	6080	(heat adj sink) same electronics
2	BRS	4	((heat adj sink) same electronics) and 165/135.ccls.
3	BRS	254	motor and fin and (heat near dissipat\$) and electronic and (air adj flow)
4	BRS	0	motor and (fin near3 mount) and (heat near insulat\$) and electronic and (air adj flow)
5	BRS	5	motor and (fin same mount) and (heat near3 insulat\$) and electronic and (air adj flow)
6	BRS	0	motor and (fin same electronics same mount) and ((heating or heat) near3 insulat\$)
7	BRS	776	motor and electronics and (mounting or mount) and ((heating or heat) near3 insulat\$)
8	BRS	0	motor and electronics and (mounting or mount) and ((heating or heat) near3 insulat\$) and (310/\$.ccls or 361/\$.ccls)
9	BRS	0	motor and electronics and (mounting or mount) and ((heating or heat) near3 insulat\$) and (310/\$.ccls or 318/\$.ccls or 248/\$.ccls)
10	BRS	0	248/\$.ccls

	DBs	Time Stamp	Comments	Error Definition
1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/02 16:08		
2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 17:33		
3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 18:09		
4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 18:11		Truncation Overflow. Return string from Server is: 5`1676214
5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 18:14		Truncation Overflow. Return string from Server is: 5`1676214
6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 18:15		Truncation Overflow. Return string from Server is: 5`1676214
7	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 18:20		Truncation Overflow. Return string from Server is: 5`1676214
8	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/05 14:04		Truncation Overflow. Return string from Server is: 5`1676214
9	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 18:24		Truncation Overflow. Return string from Server is: 5`1676214
10	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 18:23		

	Errors
1	0
2	0
3	0
4	1
5	1
6	1
7	1
8	1
9	1
10	0

	Type	Hits	Search Text
11	BRS	776	motor and electronics and (mounting or mount) and ((heating or heat) near3 insulat\$) and (electronic or controller)
12	BRS	60	heat with fin with insulat\$ with electronic

	DBs	Time Stamp	Comments	Error Definition
11	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/04 18:29		Truncation Overflow. Return string from Server is: 5`1676214
12	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/04/05 10:53		Truncation Overflow. Return string from Server is: 5`2142401

	Errors
11	1
12	1

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	0	d13/112.ccls	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM TDB	2001/04/05 13:00
2	BRS	L2	0	d13/112/ccls	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM TDB	2001/04/05 12:59
3	BRS	L3	205	d13/112.ccls.	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM TDB	2001/04/05 13:00
4	BRS	L4	1	d13/("112" or "114" or "115" or "116" or "179").ccls.	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM TDB	2001/04/05 13:01
5	BRS	L5	550	d13/112.ccls. or d13/114.ccls. or d13/115.ccls. or d13/116.ccls. or d13/179.ccls.	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM TDB	2001/04/05 13:02

	Comments	Error Definition	Errors
1			0
2			0
3			0
4			0
5			0

	Type	L #	Hits	Search Text	DBs	Time Stamp
6	BRS	L6	81	motor and electronics and (mounting or mount) and ((heating or heat) near3 insulat\$) and (310/\$.ccls. or 361/\$.ccls.)	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM TDB	2001/04/05 14:10

	Comments	Error Definition	Errors
6		Truncation Overflow. Return string from Server is: 5`1676227	1